Service Bulletin

Enriching Lives

Service Bulletin No. G0012 /11 **Date: - 10.03.2011**

Engine Type : 2R1040, 3R1040 & 4R1040

Application Code : 2H.9075, 2H.9080, 2H.3065, 2H.3070,
3H.9075, 3H.9080, 3H.3065 , 3H.3070
4H.9075, 4H.9080, 4H.3065, 4H.3045 (Engine codes)

Name of the Part : Air Cleaner assly (3H.415.10.0.00).

Modification : Change and modified the Air cleaner assly for better performance.

Reason for Modification:

1. The new Air cleaner performance is better than old air cleaner.
2. Less Air flow restriction.
3. Easy for maintenance.

Details of Modifications:

New part Number	Description	Old Part Number	Description
3H.415.10.0.00	Air Cleaner Assly	2H.277.20.0.00	Air Cleaner Assly
04.586.03.0.00	Air Cleaner Element	2H.277.05.0.00	Air Cleaner element.
4H.404.02.0.00	Bkt. For Air Cleaner	2H.277.02.0.00	Bkt.For Air Cleaner.
4H.404.03.0.00	Hose	2H.277.03.0.00	Hose
4H.404.03.0.00	Adaptor	4H.174.02.0.00	Adaptor
4H.169.01.0.00	Rain Cap	NA	
04.588.04.0.00	Spacer Ring	NA	

Date of Implementation w.e.f. 1st May 2011.

This document has been created digitally and is valid without a signature.

Global Customer Support

Export

PS(G) / 10/03/2011

SERVICE

KIRLOSKAR OIL ENGINES LIMITED